

**NAVAL ELECTRICAL BRANCH—SPARE GEAR, FITTINGS,  
DRAWINGS—RESPONSIBILITY FOR.**

The Electrical Officer of the ship is to assume responsibility for electrical spare gear, fittings, and drawings, formerly on the charge of the Engineer or Torpedo Warrant Officer, listed in forms D.320 and A.D. 791, respectively.

2. Should there be no space available for new stowages for the spare parts due to be transferred to the custody of the Electrical Officer, arrangements should be made between the officers concerned for the parts to remain in the same box (es) with the mechanical equipment.

3. Lists of drawings, instruction books, fittings, and spare parts in charge of the Electrical Officer are to be compiled in accordance with memorandum A.D.791, which is to be amended as follows:—

(a) Heading and paragraph 1, delete “Torpedo Warrant” and substitute “Electrical”.

(b) Paragraphs 2 and 3, delete “Spare Parts of Torpedo Tubes”.

4. For ships already in service, lists of drawings, Instruction books and parts, on charge of the Electrical Officer, are to be prepared in triplicate by ships’ officers. Completed and signed copies are to be forwarded—one to Navy Office and one to the Dockyard to which the ship is attached for use with yard copy of list.

5. When the Electrical Officer’s new list is completed other ships’ officers concerned are to raise forms A.D.526 in accordance with form A.D.791.

6. Forms for compiling new lists should be demanded from the Superintending Naval Store Officer, Sydney.

(612/217/1875.)